

Greetings Spring Lake Residents,

With the conclusion of the 1st alum treatment, we wanted to update you on the initial results. Please find a series of pre/post photos below with lake clarity measurements recorded. The next treatment for Spring Lake will be in approximately 6 months, with monthly water quality samples being collected to monitor the lake. We are very thankful for the residents of Spring Lake in refraining from boating while the 3 day application took place!

Before Treatment:




5 Days After Treatment:



Application:



Secchi depth measurements post treatment:



The secchi reading (measurement for water clarity) taken prior to alum treatment was 2.9 feet (on 12-5-16). A secchi measurement was taken 3 days after alum treatment (on 1-16-17) which was 7.9 feet and 8.5 feet on 1-18-17.